TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT Page 1 of 3 <u>78721</u> 4602 Munson St <u> Austin</u> Zip Code Inspected Address **SCOPE OF INSPECTION** This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, deta structure will not be included in this inspection report unless specifically noted in Section 5 of this report. ds, detached garages, lean-tos, fences, guest houses or any other В This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessary removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) (including the sunace appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.

Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment, has C. rendered the pest(s) inactive.

If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engi qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qual THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. E. ineers or builders performed by a qualified expert. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the G structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.

There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options. Η. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.

If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. J. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture. HI Services
Name of Inspection Company 1B. 0713842 SPCS Business License Number 1A. TAHI RT FORWARDED TO: Title Company or Mortgagee L. Purchaser of Service L. Seller L. Ag (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy) The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected 5. Primary Structure Only List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection) Yes 🗵 No  $\square$ 6A. Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B. 6B. The obstructed or inaccessible areas include but are not limited to the following:  $|\mathsf{x}|$ |X||X|Attic Insulated area of attic Plumbing Areas Planter box abutting structure  $\boxtimes$  $\square$  $\square$ Crawl Space Soil Grade Too High X X Heavy Foliage Eaves Weepholes  $\times$ Other Specify: Various Areas Obstructed (Pre-Existing Structure), Furniture/Storage 7A. Conditions conducive to wood destroying insect infestation? (Refer to Part J, Scope of Inspection) If "Yes" specify in 7B. Yes 🗵 No  $\square$ 7B. Conducive Conditions include but are not limited to: Wood to Ground Contact (G) Formboards left in place (I) Excessive Moisture (J) Debris under or around structure (K) Footing too low or soil line too high (L)  $\boxtimes$ Wood Rot (M) Heavy Foliage (N) Wood Pile in Contact with Structure (Q) П Planter box abutting structure (O) Wooden Fence in Contact with the Structure (R) Other (C) Specify: Slab covered Insufficient ventilation (T) 8. Inspection Reveals Visible Evidence in or on the structure: Active Infestation Previous Infestation **Previous Treatment** Yes 🗆 No 🗵 Yes 🗵 No 🗆 Yes 🗆 No 🗵 8A. Subterranean Termites

No 🗵

No 🗵

No 🗵

No 🗵

has been observed in the following areas: utility closet/trim near cold joint

Yes  $\square$ 

Yes 🗌

Yes 🗌

Yes 🗆

If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed on the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspection)

8F. Explanation of signs of previous treatment (including pesticides, baits, existing treatment stickers or other methods) identified:  $\underline{N/A}$ 

Yes 🗌

Yes 🗌

Yes 🗌

Yes 🗌

No 🗵

Yes 🗌

Yes 🗆

Yes 🗌

Yes  $\square$ 

Buver's Initials

8B. Drywood Termites

8D. Carpenter Ants

Specify:

8C. Formosan Termites

8E. Other Wood Destroying Insects

8G. Visible evidence of: sub termites

# TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

The conditions conducive to insect infestation reported in 7A & 7B:  9. Will be or has been mechanically corrected by inspecting company:  If "Yes", specify corrections: N / A						Yes 🗆	No 🗵
9A. Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment as identified in Section 8. (Refer to Part G, H and I, Scope of Inspection)  9B. A preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is recommended as follows:  Specify reason: See Section 7 and 8 For Details: (C)(L)  Refer to Scope of Inspection Part J						Yes X	No □ No □
10A. This compan	by has treated or is treating the structure for an earn termites, the treatment was:  ood termites or related insets, the treatment	Partial [	] s	cts: N/A  pot	Bait		Other
This company has	reatment by Inspecting Company s a contract or warranty in effect for contro No List Insects: s", copy(ies) of warranty and treatmen	ol of the following wood	tached.	sects:	Nar	me of Pesticide	e, Bait or Other Method
	st draw a diagram including approximate ation; A-Active; P-Previous; D-Drywood <sup>**</sup> tther(s) - Specify	perimeter measuremen	nts and indicat	e active or previou			
	(C) Slab covered						
			15'	<b>&gt;</b>	20'		
		15' (C)	Cold joint	ADD-ON		18' (P	S) Previous termite damage @ trim near cold joint _(L) Soil line issue
	Extensive termite damage (Utility closet)	10' 4' (PS) 12'		PAINT/REM LIMITATIO	7 7 T	22'	
				40'			
Additional Comme	ents <u>Full interior/ext</u>	erior treat	ment a	dvised			
	ompany for which I am acting have had, is associated in any way with any party to		emplate havin	g any interest in th	ne property	. I do further s	tate that neither I nor the company
Signatures: 11A. Andrew	rS. Jordan		Notice	of Inspection Was Electric Breaker		or Near	
Inspector  Approved: 11B. Andrew Jordan0702346 (512)-788-1001				Water Heater Cl Bath Trap Access Beneath the Kito Date Posted We	ss chen Sink	□ □ □	rch 27, 2019
Certified I have received the I understand that it	ed Applicator and Certified Applicator Lice e original or a legible copy of this form. I my inspector may provide additional infor nation is attached, list number of pages:	ense Number Stater have read and underst mation as an addendur	ment of Purch and any recon	naser nmendations mad			Date
	naser of Property or their Designee		Date				

## TREATMENT PLAN AND ESTIMATES



PROPOSED TREATMENT: CHEMICAL TO BE USED: ADDITIONAL CHEMICALS: N/A STRUCTURE TYPE:

TAHI SERVICES REP: Andrew Jordan CA#0702346 Andrew S. Jordan

WARRANTY: N/A

#### Subterranean Termite Post-Construction Treatment Disclosure For Each Estimate

When an estimate or proposal for termite treatment is submitted to a consumer the pest control company must provide the following written disclosure information: For all treatments there will be a diagram showing exactly what will be treated. Treatment specifications and warranties for those treatments may vary widely. Review the pesticide label provided to you for minimum treatment specification. If you have any questions, contact the pest control company or the Texas Department of Agriculture, P.O. Box 12847, Austin, Texas 78711-2847. Telephone number (866) 918-4481 or Fax: 888-232-2567. Documentation shall also include but is not limited to approximate perimeter measurement of the structure, areas of active or previous termite activity, the concentration of any liquid termiticide application to be used or the minimum number of baiting systems installed or the square footage if a barrier is installed. The consumer is advised to review all this information and the pesticide label for explanations of the proposed treatment and compare this with any other proposal or estimate they may receive.

#### **Definitions of Treatment**

A subterranean termite treatment may be a partial treatment or a spot treatment using termiticide, approved physical barriers or a baiting system. These types of treatments are defined as follows:

#### **Partial Treatment**

This technique allows a wide variety of treatment strategies but is more involved than a spot treatment. (See definition below.) Ex: treatment of some or all of the perimeter, bath traps, expansion joints, stress cracks, portions of framing, walls and bait locations.

<u>Pier and Beam</u>: Generally defined as the treatment of the outer perimeter including porches, patios and treatment of the attached garage. In the crawl space, treatment would include any soil to structure contacts as well as removal of any wood debris on the ground.

<u>Slab Construction</u>: Generally defined as treatment of the perimeter and all known slab penetrations as well as any known expansion joints or stress cracks.

## **Spot Treatment**

Any treatment which concerns a limited, defined area less than ten (10) linear or square feet that is intended to protect a specific location or "spot." Often there are adjacent areas susceptible to termite infestation, which are not treated.

### **Baiting System**

This type of treatment may include interior and/or perimeter placement of monitoring or baiting systems along with routine inspection intervals. The baiting technique may include one or more baiting locations as prescribed by the product label and instructions.

### Barriers

If a physical device is used, the square footage of the physical device must be recorded and a diagram describing the installation will be provided.

WARRANTY information provided includes the complete details any warranty provided and the following:

- Time Period of the Warranty
- Renewal Options and Cost
- Obligations of the Contracting Parties
- Conditions that could develop which would void the warranty
- Name of the pest control company responsible for the warranty.

If the warranty does not include the entire structure treated, the areas included in the warranty are: (specify)

A copy of the consumer information sheet has been made available to the appropriate party.

### **Additional Information**

In addition to the information listed above the following information must also be included on the diagram: Known wood destroying insect activity, conducive conditions, type of construction, construction details, and any other information about construction relevant to the treatment proposal.

Licensed and regulated by: Texas Department of Agriculture P.O. Box 12847, Austin, Texas 78711-2847, Phone (866) 918-4481, (FAX) 888-232-2567


Revised 07/30/2010

#### LEGEND:

Present or Previous Activity and Type: (A) - Active (P) - Previous (S) - Subterranean Termites (F) - Formosan Termites (W) Drywood Termites

Treatment Procedures: (T) - Trenching (D) - Drilling (R) - Rodding (Z) - Foaming (U) - Spraying

Conducive Conditions: See Section 7B of the associated Texas Official Wood Destroying Insect Report -(K)(O)(T)(G)(L)(Q)(C)(I)(M)(R)(J)(N)




#### **TAHI SERVICES**

5209 Downs Dr. Austin, TX 78721

Phone (512) 788-1001 andy@atxinspect.com

CA# 0702346



INVOICE NUMBER 20190327WDI-Munson INVOICE DATE 03/27/2019

DESCRIPTION	PRICE	AMOUNT
	SUBTOTAL	\$0.00
	TAX	\$0.00
	TOTAL	\$0.00
BALANCE DUE ONLY IF SERVICE REQUESTED	BALANCE DUE	\$0.00
		<b>PAID</b>

### THANK YOU FOR YOUR BUSINESS!

Please Make All Checks Payable to: TAHI Services PLLC 3571 Far West Blvd #101, Austin, TX 78731